

# Software Release Note Vocality Gateway Suite 7.1.4

Date of software release: 25 April 2023 Release Note date: 25 April 2023 Release Note version: 1.1 Release Identification: 7.1.4-d183edc26

## **Purpose of Release**

This minor release contains stability improvements to the RoIP LTE functionality. It is thus recommended that all customers upgrade to this release.

#### **Document History**

Version	<u>Date</u>	<u>Details</u>
1.0	25 April 2023	Initial Draft

# Hardware Affected

This release is targeted to all versions of Cubic's RoIP, M3X RoIP and M3-SE-MFGW.

## **Pre-Requisites**

This release should only be installed on Cubic's RoIP products currently running release 4.17.2 and later.

For earlier releases, please use the <u>Software Portal</u> to upgrade to 4.17.2 first.



# **Upgrade Instructions**

Before starting the upgrade to 7.1.4, please check whether you are connected to the device via an IP address or the admin.vocality.com DNS name. If the latter, please follow these instructions before performing the upgrade.

The admin.vocality.com domain name was removed in release 7.1.2, so you will need to access the device via its LAN IP address after the upgrade, instead of admin.vocality.com. Therefore before upgrading, take careful note of the LAN IP Addresses for the RoIP.

– node0001	
Vocality RolP	۲
Serial Number	114706
Software Version	7.1.2
LAN IP	192.168.0.199
eth1 IP	192.168.1.212
Secure	٢
Failover	9

It's prudent to have a backup of the RoIP configuration. This can be done in Platform->Config Files.

Once you have completed the upgrade:-

- Open a new browser tab/window.
- Enter the IP address of the RoIP to connect to the user interface.
- Accept the browser security warning.
- You should now have 7.1.4 installed on the RoIP.



#### AT&T Users

Please ensure the upgrade is performed online. If you need to do an offline upgrade, please contact a member of the Cubic support staff for assistance.

# **Key Features and Enhancements**

• Further improvements to cellular handling to improve long term stability of LTE connections. This includes disabling SIM hot swap functionality. If the SIM card needs changing, it should be done with the device powered off.

## **Bug Fixes**

Ensure vocsupport user can delete MCPTT PCAP logging file

## **Component Version Numbers**

Changes highlighted.

- vocality\_api-2.1.0
- vocality\_database-1.3.0
- vocality\_dispatch-1.5.0
- vocality\_filesystem-1.1.0
- vocality\_mcpttgateway-1.3.1
- vocality\_modemupgrade-1.2.4
- vocality\_multibearer-3.4.1
- vocality\_nodemanager-4.16.6
- vocality\_nodeui-4.18.3
- vocality\_password-1.1.0
- vocality\_picfirmware-1.1.0
- vocality\_radiogateway-4.7.0
- vocality\_registry-3.3.0
- vocality\_registryclient-3.3.0
- vocality\_release-7.1.4
- vocality\_secure-4.2.2
- vocality\_serial-3.2.0
- vocality\_utils-2.2.2

© 2023 Cubic Corporation. All Rights Reserved.